

# Barton House

January2024


Barton House Structure







### **Investigation Locations**

#### Phase 1 and Phase 2










#### **Details**




Flank wall and slabs
Approx 85% effective

**Internal walls and slabs** 







#### **External wall condition**



Original construction needs additional support to be OK in the event of a fire.



## Goal post strengthening



#### **Barton House Remedial Works Timeline**

